Menlo Park Notebook #236 [N-81-03-11]

This notebook covers the period March-April and December 1881. Most of the entries are by Francis Jehl. The book contains notes and calculations relating to meter experiments and to tests of dynamos and wires. Included also is a summary by Edward L. Nichols of the meter experiments. The label on the front cover is marked "Francis Jehl." The book contains 278 numbered pages. The last few pages have been torn out of the book.

Blank pages not filmed: 106-225, 228-275.

1 : 4 °

2 40

4 : 1 :: 200 : 50

4 / x = 200 / 20

x

4) 200 (50

LIBRARY OF THE

BOARD OF PATENT CONTROL,

120 BROADWAY, NEW YORK.

From Library
GENERAL ELECTRIC
44 & Broad St. Mfg.
May 1, 1896

March 14 1896

Measured a German Silver
its resistance was .019 ohms

970 : 30 : x : .019

970

13090

1683

30) 18139 (.60
180
013
00

1800

Res of Cu plates all .6 ohms

Plate 26. .500 / 150 / 80. | 411.9

Current on at 10.53 amm.

The Solution is a Saturation of pure (C.P.) of Cu S 4.

Candles of lamp 16.

Started at 12 P.M.

Stated at 1.22. P.M.

2 Stopped current on
Hen at 4.10 Weight 412.1

26, 689.3.5

67
37
40
70

Running 31.55 gives 9 hr minutes 61/2 3 5/3
15 5
5 5

Started again at 4.55
Stopped at 6.9 P.M

Current on at 9.14.5 412 grams

Set up my Meter The resistance of the shunt I used was 0.1 ohm had the reverser on all right and with eight Camps it went as follows

Struck at
11.49 A.M 1
#2 12.45 P.M 2 56 Minutes
~~1240~~ 1/2 minutes to 2 1 55.5 minutes
2

Commenced again at 2.58.
dropped at 4.12
Struck at 5.18

March 11, 1881.

Summary of Meter Experiments.

—Freezing Points.—

(1) Ordinary solutions Cu $SO_4 + H_2O$ freeze just under 0°C.

Addition of Glycerine lowers freezing point.

As much as 40% Glycerine can be added without interfering with the plating process. With 40% Glycerine the freezing point is below −20°C.

The Glycerine increases the resistance very materially.

Influence of strength of solution.

(2) About 20% parts Cu SO_4 to 100 H_2O is as strong a solution as can be used at low temperatures — (See Watts' Dict. on Saturation points of Cu SO_4 solutions)

The rate of the meter is within large limits independent of the strength of solution provided always that the

current remains constant

Influence of temperature upon rate of Motor.

$CuSO_4$ increase in conductivity with the temperature.

(See Riedemann, Fuhlbeers Physik Ba IV p 491)

For 18.7 parts $CuSO_4 + 100 H_2O$

Riedemann formula—

Temps.	Res.
0°C	1.60
20° "	0.738
40° "	0.523
60° "	0.384
80° "	0.330

(3) In case of metals - Matthiessen gives formula: { Poggendorff's Annalen 115 p 122.

$$C = C_0 (1 - 0.0037674 t + 0.0000083442 t)$$

where C = Conductivity

C_0 = " at 0°

t = temps.

1 3

4

1.077
3.231
734
3.979
1.329
3
3.987

3.33
3.98
4.31

This gives.

Temps.	Res.
0°C	1.00
20° "	1.077
40° "	1.160
80° "	1.329

In consequence of these relations a circuit containing solutions and metals can always be so arranged that its conductivity shall be independent of the temperatures.

If we use a 20% Solution of SO_4 & Copper. — Find the proper ratio of metal to Solution to be 3:11

The rate of the meter at different temperatures by actual test was found to be. — When the solution only was changed and the metal parts of the

circuit remained at room temperature to be;

Solution 18 %.

Oscillations per hour.	Temp.
3.5	0°C
4.1	10°C
4.8	20°C
5.5	30°C
6.2	40°C

From this the compensation can be calculated; by comparison with Wiedemann's results the other errors of the instruments found.

Nichols.





March 16, 1881.

METER TEST

From 2 to 1 = 12 M to 12.15 P.M
" 1 " 2 = 12.15 P.M. to 12.32 "
" 2 " 1 = 12.32 " " 12.45 "
Not Certain { " 1 " 2 = 12.45 " " 1 " "
" 2 " 1 = 1 " " 1.15 "
" 1 " 2 = 1.15 " " 1.46 "
" 2 " 1 = 1.46 P.M. to 2.41/2 "
" 1 " 2 = 2.41/2 " " 2.271/2 "
" 2 " 1 = 2.271/2 " " 2.47 11/12 "
" 1 " 2 = 2.47 11/12 " " 3.12 1/4 "
" 2 " 1 = 3.12 1/4 " "

From 2 to 1 = 3.50 5/6 P.M. to 4.21 11/12 P.M
Engines stopped twice - 4"

From 1 to 2 = 4.21 11/12 P.M. to 4.47 3/4 P.M
" 2 " 1 = 4.47 3/4 " " 5.13 1/2 "
" 1 " 2 = 5.13 1/2 " " 5.36 11/12 "
" 2 " 1 = 5.36 11/12 " "

Test on Large Dynamo

March 16

magnet	armature	Speed	REMARKS
0	3-3	240	Permanent magnetism
14-13.5	14-13.5	244	
13	24.5-24	222	
30	37-37		
35	38-38		
	42-42		

magnet	armature	speed

March 16 1881

magnet armature spread

Water experiments March 17 1881

No 1 Weight 669.2 grams

Date March	Weight	Time
	669.2	
18	675.6	369"

No 2 Weight 668.1 grams

March		Time
17	668.1	
18	625.1	368"

22 No 3 weight 598.9 grains

Date		
17	598.9	
18	599.	368

No 4 weight 804.6 grains 23

17	804.6	
18	804.8	367

24 No 5 weight 792.3 grams

Date		
17	792.3	
18	792.4	367

No 6 weight 690. 25

1	690	
18	690.1	366

26 No 7 weight 714 grams

17	714	
18	714	366

No 8 weight 6548

27

Date		
17	6548	
18	6548	366

28

Copper Plate put into a Solution without Current

March 18	weight	411.8 grains
19	"	411.9
March 26		411.7
29		411.9
April 13		412.1



29

Copper Plate put in water

March 18	weight	634.7 grains
19		634.7

30

Copper plate in these solutions as
tests are made

17 925.12 grams 2.8 ¹
18 924.77
19 63415 grms —

31

Sunday March 26
1911

260 of 65° 71 27 B

1000
260
740) 2600 (.35
2220
3800

1000
274
126) 2740 (.21
2178
5620
5082

1000
566
434) 566 (1.3
434
1320
1302

760

.37 2
111
37
1.11 1.

1.

Y=1
1
1X1
1+1

.10
1/3
1.33 .3
13) 130 (.23
26
40
39

.23
3
.69

Finding Number 26 at 617

1432

568) Tally .76 plus

568 : 1

568) 4320 (.8

4544

568) 4320 (.76

3776

3440

3408

1.00

.76
.24
304
152
1) .1824 (.1

.37
2
.74

.37
.76

.37
.74

4

.37
.76
222
259
.2812

.37
.76
1.13

1.13) .2 5 13 00 (.24
226
552
452
1000

24
72

.76

3
2
1 1/2 .2

$\frac{9}{16}$ or 14 C.M and a thumb peak between it, 4 in wide $3\frac{1}{2}$ long



.015
.150

15
.75
.60

900 : 100 :: x : .0157

.0157 × 900 = 14.13

100 | 14.1300 (.160

1000
895
105

895 : 105 :: x : .0157

.0157 × 895 = 14.0515

105 | 16.7365 (.15

62 23/35

both cell = .15 ohms

963
087

963 : 37 ?? × .087

963
.087
5741
7704
963

37) 16.00.81 (.48
148
320
296

75.8 = 1

75.8) 1.000 (.013
758
2420
2274

75.8 put = 1 ohms

45) 75.8

100) 75.8 (.758

.758

.758 ×
45
3790
3032
34110

.15
45
.45
1 5
.6 0

15) 45 (3
45

.7

March 27 1884

Cow cell plate
weights 612.7 grams
612.7

Started at 11.4 AM
Stopped at 6.4 P.M

609.4 grams
610.6

610.6
609.4
1.2

other plate weights

348.7 grams
389.6 grams
340.

340
339.6
.4



Plate No 7

855. grains
965.5 grains
855
1105

32

18.44 mg
min

18.3 grains

.305

.0005 grains lost
.1647
2305
.0000
.00002638 mill
223
.213
.326

Plate No 6

688.7 grains
799.
688
1103 18.3 grains avoirdupois

6110 grains in 6 ounces
18.3 avt

.326
60) 18.3 (.305 12.656
180 300 1173600

60) .305 (.0005
300
5
60 = 1
326 65

.005
.305

.826

1% 250. .125 100

$$\mathcal{E} \quad \mathcal{C} = \frac{\mathcal{E}}{R} \qquad CR = \mathcal{E}$$

11 4/8 4

1% .101 / .101 + .6

1% .6 / .101 + .6

61) .326 305 21

.005 / .305

.005 / 0.00 50 / 0.00 0 60 / how 1 8.0 00 10 / 10 how 1 8 00 0 0

4) 180 / 45 Tally / 135 mile

cell) .101 / .61

.60 / .61

.0017 m / 60 / 18.001

Travelling through 25 / 1881

Cur C through cell =

$1 \times \frac{.01}{.01+.6} = \frac{.01}{.61}$

C through S =

$1 \times \frac{.6}{.01+.6} = \frac{.60}{.61}$

$1^{mg} = \frac{.015}{45}\ gr = \frac{135}{.015}$

675

$.675$ grains $\quad 135$

2.025

.326 mm per $\square''$

61 | .326 (.005 mm per second

.005 / 60

.300 per minute / 60

18.000 per hour / 10

4 | 180.000 10 hours

45 min. Tally cell

185 min.

45 mg or .675 grains or cell. 10 hr with

2.028 gr or 135 mg = 10 hr

Comm. Q in

180 mg in 10 hr through
ceee and C.R.

4/180.
45. goes in tubing
and 135 out in R

1/4 | 45
11 1/4 mg in tally cell

11 1/4
3
33 3/4 goes in ordinary cell

11 1/4
.015
5 5
1.13 3/4
.168 3/4 gr

3.3 2/4
.045
166
33 11 1/4
.406 1/4

11.25 mg
168.75 gr } 10 hr

33.75 mg
.406.25 gr } 10 hr

2 | 33.75
16.87 at 6 hr
30
506.10

133.
11
22.

70
30
2100.
1
4200
2 1 0 0
2 1 0 0






3
3
1.5

52 Thursday 1911

Length of German Silver strip

$18\frac{3}{8}$ long + $1\frac{1}{4}$ inches wide

Resistance of 1 foot of No 28 gauge Cu wire at the Reference Temperature

.0187385
530
562155 0 6
149908 0
170) 15.9529550 (.09144
1530
252
170
829
680
1495
1360

53.

April 7.

Test of brass resistance wire

D = .1051

L = 10 ft 7½"

T = 78°.7 = 26°C

R = 830 − 170 = .207406 Ohms
.0187385

830 : 170 : X : .0187385
530
562155 0
149908 0
170) 15.9529550 (.20740
1400
1299
1190
.207406
690
680
1050

Res = .207406 of an alum

.05 / .051 / 256 / .002601

7/12 | 7.0 / 6.0 / 1.00 / 96 / 4 (.58)

.002601 = D²

9.829 / .002601 × 10.58

9.829
10.58
78632
49145
9829
103.99042 / .002601 = 39981.

.002601 | 103.990820 (7.18 / 94 / 4.25 / 829 / 9.718 / 9.680 / 2 | 9.668 / 9.829 / 39981.0

.002601 | 103.990820
78 03 ××××
25 9 80
23 40 9
25 51 6
23 40 9
2 10 92
2 08 08
28 40
26 01
2 39 0

26 C°

1.003824
26
2 2944
7 648
1.099424

39981.
1.10

39981.
1.10
39981 0
39.981
439791 0

9.829 × 10.58 × 1.10

51²
51
51
255
2601 / 9.8290 .00377
7803
20260
18207
26530
18207
2323

.00377
10.58
3016
1885
377
.0398866
1.10
3988660
398866
.04387526 0 C. Ans.

9.8 2 9
10.5 8
7 8 6 3 2
4 9 1 4 5
9 8 2 9
10 3.9 9 0 8 2
1.1 0
1 0 3 9 9 0 8 2 0
1 0 3 9 9 0 8 2

51
51
25 5 1
2601

2601) 1 1 4 3 8 9 1 . 0 2 0 (.0 4 3 9 7 9
1 0 4 0 4
1 0 3 7 9
7 8 0 3
2 5 4 6 9
2 3 4 0 9
2 0 6 0 0
1 8 2 0 7
2 3 9 8 2
2 3 4 0 9
5 2 3 0

.00430
.0043
10.5 8
2154
43
.045494

1000) 4.3 0 5 2 (.0 0 4 3 0 2
3 0 5 2
3 0 0 0
5 2 0

2.1 (1

.043979 Res of pure Copper
at 75° Di = 51 length
10.58 ft

of Sample to be tested
length 10.58 ft Di = 51
Res = ~~.207406~~ .09148

.043979 : .207406 :: X : 100

.207406) .043979 0 0 (.2

.2
-04) .04 (.2

.043979 C.P.C
.09148 Cmpe

.09148) .043979 (.48 per cent
36592
738700
731840
8



60)120 (1.2
60
120
120

14.200
12
36
36
56
48
80
72
8

1.12
603
7236
756

1.12
2.04

1.2
5
6.0

14.20
10

1(12
1.2
2.0

1/6 of an ohm for distribution
1/6 for return
1/10 for end

were no .028 = 75.8 Ft per ohm
10)75.80 (7.58 = .1 ohms
70
58
50
80

6)75.8 (12.63 feet = 1/6 of an ohms.
6
15
38
30
8
10)12.6 (1.26
10
26
20
6

1420 cm

14

1420 CM — 100 ohms
wire with Insulation
.010 Dia
Circumference 2.5 CM
length of Spool 2 inches

2.5 c.m
2
5 0 0 0
1 0 0 0

10/2000

2.5
2
500.
1500

6/60 (.1

1/6/10 (.16
60
40

1/10/12 (.1
10
2

1/7/30 (.14
28
2

1/8/10 (1.2
8
2

1/9/11 (.11
9
2

100) 200 (.02
.04

100) 300 (3
.01

300 = 2V
1 = 150

100) 2.00 (.02
2 00
.02

100) 150 (
1.5
6.0
2

100) 332 (3.32
3 0
2 0
6.64

3
332.5
3265
6.0

325

332.5 Com
326 5 Sud

334.5
325
6.0

Made 10 100 ohms Bobbins and Soldered them on to the wire. 1/6 of ohms and 1/6 returns. Making a resistance of 2/6 of an ohm. Ends of the chromium gold a fall of 2%. Then Made one 100 ohms spool and total Res of line 12 of and ohms and also at a fall of 2%.



13
14
15

10 16

90

150

15.5

$C = \frac{\varepsilon}{R}$ $\varepsilon = CR$ $R = \frac{\varepsilon}{C}$

$CR = \varepsilon$

$\frac{1}{5}$ $\frac{1}{12}$ $\frac{1}{60}$

$\frac{1}{5.33} \approx .05$

45
55

April 14 1881

Large Cu 676.1 grains 695.8

Sm. Cu 462.1 grains 472.

695.8 − 676.1 = 19.7 grains

472.0 − 462.1 = 9.9

9.9

Large 702 − 695.8 = 6.2

4738 − 4720 = 18

Sm 473.8 − 477.5

Large 702. 714 − 702

Large 714 − 725.2 grs

Sm 477.3 − 480.8

Large 725.7 − 480.8 − 477.3 = 3.0

Sm 480.8

Large 747.8

Sm 486.4

at 8 ℔ 7 ℥.

1000 − 263 = 737

263 : 737 :: K : .0167 35

263

5621 4

11242 8

3746 6

18) 620 (3.4 737

54

263 8

737

4702709 4 (.0035

1.8) 6.2 1 (3.4

54

8.0

8

1000 − 368 = 632

3) 16.7 (5.9

27

27

3.4 Times 100

.0167 35

368

14 99 04

10 24 28

5621 4

35) 120 (3.43

105

150

140

10

6.7 7 5 5 8 4 0 10

32

4758

72

Large 1478 — 1475 − 725.7 = 22.1

Sm 486.4 − 480.3

61 | 221 (3.62
183
380
366
14

Large 877.1 — 677.1 − 747.5 = 129.3 qr

Sm 521.8 − 486.4 − 35.4

1293 | 1062 (3.6
2310
2124

ft
1145.14 to the ohm

1145.4) 10.0000 (.00087
91632
083680

1 ft of no 12 wire = .00087 ohms

12) .00522 (.000435
48
42
36
60

.000435
75
2175
3045
4) .032625
.008 ohms

Shunt R

1000
372
628

372 : 628 : X : .018385

372
36770
12861
1151
372) 12838220 (.0

628) 12838220 (.02

.018385
372
374770
101169
56215
628) 6.970.6720 (.01109 R=8
628
690
628
6267

1000
376
624

.018385
376
11243310
101169
56215
624) 7.045676760 (.011291 R.S.
624
805
624
1816
1248
5687
5596
910

.00004 47975
20
.000095950 0

.011291
.000959
.011332 Rs of Shunt
at 75°F.

2.5
3
7.5
3.5
2 8 7 5
2 2 5
2 6 2 5
2

16
2
3.2

Sq in Sur..



6.9
1

.249
6
1.494

.249
1.49
2241
996
24.9
.3701

.249
1.49
1.739

1739) 371.01 (.21
3478
2321
1739
582

3
63
21
.84

at 75°F

Rf Charge Cu Cel .249 ohms

1000
930 : 70 : X : .0187385

.0187385
930
5621550
1687155
16874655
2

70) 17.436850 (.249
140
343
280
630
630

1000) 5.185 (.005
5
185
170

Jan @			
50.25	929.5	38	939
50	932.5	36.5	938
49.75	937.		
49.50	938.5		
49.25	941.		937
49	943	29	932
48.5	946.5		
48	947.		
47.	947		
46.5	941.5		
46.	945		
45	942.5		
44	942		
43	941.		
42.5	939.5		
41	940		
40.4	939		
39.4	938.5		

Sep 27 C 953
Sm 26 994 = 3

§ 2 ... Working of the Exts

Solution Test +20°C = +168 = +687

10 others answer well

Get the $\sqrt{4096}$

)40.96(64
12)4 96(4
16

124
176

5821 c.

)58'21'69(765
49
144)9 21
9 04
152)81 69(5
76
5

)58'21'69(763
49
146)9 21(
8 76
1523)45 69(

178
00
4

)95'64'84((92
81
182)14 64(
13 64
184)100 84

)95'64'84(978
81
187)14 64(
13 09
1948)155 84(
155 84

57'198'969

)57'198'969(7566
49
1446)8 19
7 28
15106)99 89
90 66
151126)95 369
90 756

57198969 (756 3
49
145) 819
725
1506) 9489
9036
15123) 45369 (

6849216 (8276
64
162) 449
324
1647) 12521
11529
16546) 99276 (
92676

1018081 (1009
1
29) 0780
0180

1018081 (1009
1
20) 0180
81
2) 0180 (
01
200) 018081
18081
2018) (

1018081 (100
20) 01
200) 018081
1018081 (100
20) 01
0180

1018081 (1009
1
20) 01
200) 018081
18081

)9803161(9

9803161(31316

67)80
67

623)1931(
1869

6261)62611
62611

)152275 6 (1234

22)52
44

243)827
729

2464)9856
9856

)1018081(100

20)01

2009)1808 1(

When the current first
enters a deposition cell,
the cell has a high
resistance and if the
current continues to flow
its resistance will gradually
diminish. This can
be verified by actual
experiment, put the deposi-
tion cell in one arm of
the wheatson bridge and
get it balanced, and
watched. the ifield, a
current will gradually
begin to flow and you
will have to keep the field
balanced out

your resistance is
constantly diminishing
This phenomenon I
describe as follows.
When the current first
enters a cell, its resistance
is that of the liquid from
plate to plate, but when
the current begins to flow,
and by electrolysis it
takes these small particles
of copper from one plate to
the other it is evident that
the resistance is diminished
therefor its resistance being
diminished a stronger
current flows and this
takes or deposits more

than before
copper, which again
decreases the resistance
and so continues until
it reaches its limited
point, where it retains
a constant resistance
provided the Density
of the Solution is always
the same, and the
distances between the
plates is the same.
P.S. It will be noticed
that when we have
mentioned the resistance
we see its resistance
will diminish rapidly
and gradually decrease
the decrease being slower

92

and slower until it reaches its maximum point.

F. J. Lee

Large Metal 24 C =

217 : 1000 - 217 :: x : 1 = 29

Small Metal 24 C°

517 : 1000 - 517 :: x : 1.1104

The above action may be made clear by supposing that the electrolytic takes place that some sulphuric acid

93

is set free by the deposition of copper, and that this forms a good conductor this again combines with Copper & the other Metal and forms sulphate of Copper. At first the action is not so rapid as when the current has been on a little while.

F. J. Lee

910 : 90 :: K : .018738
910

18738 0
168742
1706158 0

90) 17.06158 0 (.189
806
720
860
810

18.5°C

.018738
920
374760
168742 0

80) 17.24897 60 (.215
12
409

21
3
63
21
184

.2 $\frac{a \times B}{a + B}$

1+
1.2) 2.0 (.165
12
80
72
60
60
6

1.65
495
165
.660

3 3
9
1/2

$$C = \frac{\varepsilon}{R}$$

$$CR = \varepsilon$$

$$R = \frac{\varepsilon}{C}$$

110.



Sort on 101 of an abus chart

$\frac{1}{5}$

20

80

5





June 4 1887

Test of three pieces
of Copper ..

~~fourth bar~~ also





3 1



278 Lawn dispensed No 2

Dec 25 1891

Cowell	1	2.25
	2	2.31
	3	2.24
	4	2.36
Stoppard	1	2.28
	2	2.20
	3	2.32
	4	2.22
Burke	1	2.03
	2	2.03
	3	2.04
	4	2.12

470) 580 (1.5
470
110

530
470) 3150 (6.7
2820
3300
3290
10

19gm = 15.43
50
7715.0

900

4) 15 2 1/5
60
60 / 1500
0
9 - 0.2 0